



MVP-50P

Diagnostic Fee	\$295*
Repairs without New Display	\$495
Repairs with New Display	\$1,495
8130-3 Airworthiness Approval Tag	\$95

MVP-50T

Diagnostic Fee	\$295*
Repairs without New Display	\$695
Repairs with New Display	\$1,695
8130-3 Airworthiness Approval Tag	\$95

CGR-30P/C

Diagnostic Fee	\$295*
Repairs without New Display	\$495
Repairs with New Display	\$895
8130-3 Airworthiness Approval Tag	\$95

UBG Instruments

Diagnostic Fee	\$95*
Repair/ Recalibrate	\$349
8130-3 Airworthiness Approval Tag	\$95

Most Other Instruments

Diagnostic Fee	\$95*
Repair/ Recalibrate	\$295
8130-3 Airworthiness Approval Tag	\$95

Most Turboprop Instruments

Diagnostic Fee	\$195*
Repair/ Recalibrate	\$395
8130-3 Airworthiness Approval Tag	\$95

EDC-33P

Diagnostic Fee	\$195*
Repair/ Recalibrate	\$295
8130-3 Airworthiness Approval Tag	\$95

EDC-33T

Diagnostic Fee	\$295*
Repair/ Recalibrate	\$495
8130-3 Airworthiness Approval Tag	\$95

Probes/ Transducers

Diagnostic Fee	\$65*
Replacement	50% off retail
8130-3 Airworthiness Approval Tag	\$95

*All products that are received will incur a diagnostic fee which will be subtracted from all repair costs.

NIST Traceability available. Please call (541) 318-6060 or email Support@iFlyEi.com for details and pricing.

In a Hurry?

Try Our Discount Trade-In Program

- Direct Replacement Unit at a 50% Discount Off Retail (trade-in required)
- New One-Year Warranty
- Less Down Time